

Salem Keizer School District

Judson Middle School RADON TESTING SAMPLE REPORT

On-site: April 2-5, 2013

Report: April 11, 2013

PURPOSE

In February comprehensive radon testing found four locations in Judson were slightly below the action level. The operation of the ventilation system was checked, adjusted and retesting of these rooms was done

CONCLUSION

Three test locations had very reduced levels of radon. The office in the Boy's Locker had a slight increase in radon.

SAMPLE RESULTS

- In February Classroom 106 had an average radon level @ 3.4 pCi/L. In April the level had decreased to 1.4 pCi/L.
- In February Classroom 309 had an average radon level @ 3.4 pCi/L. In April the level had decreased to 1.4 pCi/L.
- In February the Media office had an average radon level @ 2.7 pCi/L. In April the level had decreased to 1.3 pCi/L.
- In February the Boys Locker Room office had an average radon level @ 3.0 pCi/L. In April the level had increased to 3.6 pCi/L.

RECOMMENDATION

Recheck the operation of the ventilation system in the office located in the Boy's Locker Room. Increase the amount of air delivered to the room.

April 9, 2013

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

SK

JUDSON

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
4601899	106	2013-04-02 @ 1:00 pm	2013-04-05 @ 4:00 pm	1.4	2013-04-09
4601901	309	2013-04-02 @ 1:00 pm	2013-04-05 @ 4:00 pm	1.4	2013-04-09
4601900	BOY'S LOCKER RM	2013-04-02 @ 1:00 pm	2013-04-05 @ 4:00 pm	3.6	2013-04-09
4601902	MEDIA OFFICE	2013-04-02 @ 1:00 pm	2013-04-05 @ 4:00 pm	1.3	2013-04-09

Air Chek, Inc. 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498