

## Waldo Middle School - 2021 Drinking Water Sampling Results

<b>Inst. Name:</b>	Salem-Keizer Public Schools
<b>Inst. ID #:</b>	N/A
<b>School Name:</b>	Waldo Middle School
<b>Building ID #:</b>	21423500

Fixture ID # Coding		
DW = Drinking Water Fountain		SF = Staff/Office Faucet
WC = Water Cooler (Chiller)		KF = Kitchen/Food Prep
WB = Water Bottle Filler		IM = Ice Machine
CF = Classroom Faucet		SH = Shower Head
BF = Bathroom Faucet		OS = Outside Spigot
NS = Nurse's Office Sink		OT = Other (Specify)

Fixture Location/Description	Fixture ID # (include coding from key above)	Sample Date	Sample ID	Result (ppb)	Above Action Level (15 ppb)
Nurse's Room	21423500-001-DW	2021-06-24	6242021-21423500-001-DW	<1	No
Staff Lounge	21423500-002-SF	2021-06-24	6242021-21423500-002-SF	<1	No
Room 104	21423500-003-DW	2021-06-24	6242021-21423500-003-DW	1.31	No
Room 104	21423500-004-CF	2021-06-24	6242021-21423500-004-CF	<1	No
Room 102	21423500-005-DW	2022-01-28	1282022-21423500-005-DW	3	No
Room 102	21423500-006-CF	2021-06-24	6242021-21423500-006-CF	<1	No
Hall at Student Store	21423500-007-DW	2021-06-24	6242021-21423500-007-DW	<1	No
Hall at Student Store	21423500-008-WB	2021-06-24	6242021-21423500-008-WB	<1	No
Kitchen Wash Sink	21423500-009-KF	2021-06-24	6242021-21423500-009-KF	1	No
Kitchen Rinse Sink	21423500-010-KF	2021-06-24	6242021-21423500-010-KF	1.14	No
Kitchen Food Prep Sink	21423500-011-KF	2021-06-24	6242021-21423500-011-KF	3.44	No
Kitchen Food Prep Sink	21423500-012-KF	2021-06-24	6242021-21423500-012-KF	<1	No
Scullery Sink	21423500-013-KF	2021-06-24	6242021-21423500-013-KF	1.49	No
Scullery Sink	21423500-014-KF	2021-06-24	6242021-21423500-014-KF	<1	No
Cafeteria at Restrooms	21423500-015-DW	2021-06-24	6242021-21423500-015-DW	<1	No
Cafeteria at Restrooms	21423500-016-DW	2021-06-24	6242021-21423500-016-DW	<1	No
Cafeteria at Restrooms	21423500-017-WB	2021-06-24	6242021-21423500-017-WB	<1	No
200 Hall Drinking Fountain	21423500-018-DW	2021-06-24	6242021-21423500-018-DW	1.58	No
Girls Locker Room	21423500-019-DW	2021-06-24	6242021-21423500-019-DW	1.61	No
East Hall at Girls Locker Room	21423500-020-DW	2021-06-24	6242021-21423500-020-DW	<1	No
Gym SW at Hall	21423500-021-DW	2021-06-24	6242021-21423500-021-DW	1.51	No
Gym NE at Exterior Wall	21423500-022-DW	2022-01-28	1282022-21423500-022-DW	<1	No
Boys Locker Room	21423500-023-DW	2021-06-24	6242021-21423500-023-DW	<1	No
Boys Locker Room Office	21423500-024-SF	2021-06-24	6242021-21423500-024-SF	<1	No
East Hall at Boys Locker Room	21423500-025-DW	2021-06-24	6242021-21423500-025-DW	<1	No
East Hall at 500 Hall	21423500-026-DW	2021-06-24	6242021-21423500-026-DW	<1	No

East Hall at 500 Hall	21423500-027-WB	2021-06-24	6242021-21423500-027-WB	<1	No
Auxiliary Gym Entryway	21423500-028-DW	2021-06-24	6242021-21423500-028-DW	<1	No
Auxiliary Gym Entryway	21423500-029-DW	2021-06-24	6242021-21423500-029-DW	<1	No
Auxiliary Gym Entryway	21423500-030-WB	2021-06-24	6242021-21423500-030-WB	<1	No
A105	21423500-031-DW	2021-06-24	6242021-21423500-031-DW	<1	No
Room 504	21423500-032-DW	2021-06-24	6242021-21423500-032-DW	<1	No
Room 504	21423500-033-CF	2021-06-24	6242021-21423500-033-CF	<1	No
Room 506	21423500-034-DW	2021-06-24	6242021-21423500-034-DW	<1	No
Room 506	21423500-035-CF	2021-06-24	6242021-21423500-035-CF	<1	No
Science Prep 508A at Exterior Wall	21423500-036-CF	2021-06-24	6242021-21423500-036-CF	<1	No
Science Prep 508A at Interior Wall	21423500-037-CF	2021-06-24	6242021-21423500-037-CF	<1	No
Science Prep 507A at Exterior Wall	21423500-038-CF	2021-06-24	6242021-21423500-038-CF	<1	No
Science Prep 507A at Interior Wall	21423500-039-CF	2021-06-24	6242021-21423500-039-CF	<1	No
Room 505	21423500-040-DW	2021-06-24	6242021-21423500-040-DW	<1	No
Room 505	21423500-041-CF	2021-06-24	6242021-21423500-041-CF	<1	No
Room 503	21423500-042-DW	2021-06-24	6242021-21423500-042-DW	<1	No
Room 503	21423500-043-CF	2021-06-24	6242021-21423500-043-CF	<1	No
Storage Room at 301/302	21423500-044-CF	2021-06-24	6242021-21423500-044-CF	2.5	No
300 Hall at Restrooms	21423500-045-DW	2021-06-24	6242021-21423500-045-DW	<1	No
Kiln Room	21423500-046-CF	2021-06-24	6242021-21423500-046-CF	9.3	No
Room 304	21423500-047-DW	2021-06-24	6242021-21423500-047-DW	4.82	No
Room 304	21423500-048-CF	2021-06-24	6242021-21423500-048-CF	10	No
Room 308	21423500-049-DW	2021-06-24	6242021-21423500-049-DW	<1	No
Room 308	21423500-050-CF	2021-06-24	6242021-21423500-050-CF	<1	No
Room 307	21423500-051-CF	2021-06-24	6242021-21423500-051-CF	<1	No
Room 310	21423500-052-DW	2021-06-24	6242021-21423500-052-DW	<1	No
Room 310	21423500-053-CF	2021-06-24	6242021-21423500-053-CF	<1	No
300 Hall at 309	21423500-054-DW	2021-06-24	6242021-21423500-054-DW	1.08	No
Room 311	21423500-055-CF	2021-06-24	6242021-21423500-055-CF	<1	No
Room 311	21423500-056-CF	2021-06-24	6242021-21423500-056-CF	<1	No
Room 311	21423500-057-CF	2021-06-24	6242021-21423500-057-CF	<1	No
Room 311	21423500-058-CF	2021-06-24	6242021-21423500-058-CF	2.02	No
Room 311	21423500-059-CF	2021-06-24	6242021-21423500-059-CF	<1	No
Room 311	21423500-060-CF	2021-06-24	6242021-21423500-060-CF	<1	No
Room 311	21423500-061-CF	2021-06-24	6242021-21423500-061-CF	<1	No
Room 216	21423500-062-DW	2021-06-24	6242021-21423500-062-DW	11.4	No
<b>Room 216</b>	<b>21423500-063-DW</b>	<b>2021-06-24</b>	<b>6242021-21423500-063-DW</b>	<b>58.8</b>	<b>Yes</b>
<b>Room 216 - Resample</b>	<b>21423500-063-DW</b>	<b>2022-02-16</b>	<b>2162022-21423500-063-DW</b>	<b>&lt;1</b>	<b>No</b>

200 Hall at 214	21423500-064-DW	2021-06-24	6242021-21423500-064-DW	1	No
100 Hall at Restrooms	21423500-065-DW	2021-06-24	6242021-21423500-065-DW	1.5	No
Room 112 North	21423500-066-DW	2021-06-24	6242021-21423500-066-DW	5.44	No
Room 112 North	21423500-067-CF	2021-06-24	6242021-21423500-067-CF	<1	No
Room 112 South	21423500-068-DW	2021-06-24	6242021-21423500-068-DW	<1	No
Room 112 South	21423500-069-CF	2021-06-24	6242021-21423500-069-CF	<1	No
Library Office	21423500-070-SF	2021-06-24	6242021-21423500-070-SF	1.21	No
Prep 108B	21423500-071-DW	2021-06-24	6242021-21423500-071-DW	2.57	No
Prep 108B	21423500-072-CF	2021-06-24	6242021-21423500-072-CF	<1	No
Health Room	21423500-073-NS	2021-06-24	6242021-21423500-073-NS	<1	No

**Notes:**

Fixtures that test above 15 ppb during the initial sampling event are taken out of service, repaired/replaced and then retested prior to returning to service.