

# INDUSTRIAL HYGIENE REPORT

## RADON TESTING REPORT

### Miller School

Report to: Vonnie B. Good, EHS Salem Keizer School District

By: Kathy Ellis, Senior Industrial Hygiene Consultant

Reviewed By: DeEtta Burrows, MSPH, CIH – Wise Steps, Inc.

On-site: December 16–19, 2014

Report: December 31, 2014

---

#### **PURPOSE**

Radon testing was done to measure the background levels in all classrooms, offices and staff work rooms that are in contact with the ground.

#### **TEST METHOD**

Radon Air-Chek short-term test devices were used in each location by placing the device 5-6 feet above the floor where it is not in direct contact with airflow from the ventilation system, windows or exterior doors. Staff were requested to keep windows closed during the testing period.

These short-term devices work by trapping room air inside the grains of charcoal within the devices, meaning that live radon gas is being captured. The analysis is performed by measuring the radiation emitted from the charcoal, which is proportional to the amount of radon that was present in the room air.

The testing occurred from Tuesday, December 16 to Friday, December 19, 2014, during normal and routine operation of the school.

#### **EPA RADON GUIDELINES**

The EPA has set an Action Level of 4.0 pCi/L (picoCuries per liter) for schools. If classrooms or buildings have radon levels at or above 4.0 pCi/L, EPA recommends that schools take action to reduce the level. These actions include:

Step 1 If your result is 4.0 pCi/L or higher take a follow-up test (Step 2) to be sure.

Step 2. Follow up with either a long-term test or a second short-term test:

#### **RESULTS and RECOMMENDATION**

No test locations were above the EPA's Action Level of 4.0 picoCuries per liter (pCi/l).

### **BACKGROUND ON RADON**

Radon is a gas that occurs in nature, seeping up from the earth. It is odorless, colorless and tasteless. Radon comes from the natural breakdown, or radioactive decay, of Uranium 238. The half-life of an individual element is relatively short. Within two weeks, about 90% of a given amount of radon gas will be gone. However, the actual health concern is for the radon decay products, called radon progeny, which carry a small static charge that allows their attachment to water vapor, dust and smoke particles in the air.

The Radon progeny can become lodged in the lung tissue when they are inhaled, and it is these particles' further radiation decay that is associated with potential lung cancer effects.

Radon can seep into buildings or schools through cracks in slab floors or porous cinderblock. It can enter around loose-fitting drainage pipes or through sump pumps.

The US EPA has set an Action Level of 4.0 pCi/L. At or above this level of radon, the EPA recommends that corrective measures should be taken to reduce the exposure to radon gas.

### **CONTROL OF RADON LEVELS IN SCHOOLS**

The major control mechanism for lowering radon levels within school buildings is use of dilution ventilation. If the amount of outside air delivered into a building increases, the radon levels should decrease.

**Sample Data Attached**

Radon test result report for:**SCHOOL  
M MILLER**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7015643	A10	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015649	A20	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015644	A20	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015645	A30	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015646	A40	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015647	A50	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015648	A60	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015650	A70	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015651	A82	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015653	B10	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015654	B20	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015655	B30	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015656	B40	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015657	B50	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015658	B60	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015659	C10	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015660	C20	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015661	C30	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015662	C40	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015663	C50	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015664	C60	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015641	D-62	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015665	D20	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015666	D30	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015668	D40	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015640	E- 20	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015638	E-10A	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015639	E-30	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015667	KITCHEN	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015652	MEDIA OFFICE	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	< 0.3	2014-12-22
7015637	PE OFFICE	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	0.6	2014-12-22
7015642	STAFF RM	2014-12-16 @ 8:00 am	2014-12-19 @ 9:00 am	0.6	2014-12-22